



Appliances properties: LEDA Werk GmbH & Co. KG - COLONA

Master data

Date of entry Feb 20, 2018

Manufacturer LEDA Werk GmbH & Co. KG

Model COLONA

Nominal heat output [kW] 1.7

Declared nominal space heating output [kW] 1.7

Continuous burning appliance

Thermal output 53,874

Type test standard DIN EN 15250

Year of testing 2015

Test laboratory RRF Rhein-Ruhr-Feuerstättenprüfstelle GmbH

Number of test laboratory 2

Number of test report RRF - 50 15 3868



Flue gas values

| | Wood |
|-----------------------------|------|
| Flue gas mass flow [g/s] | 13 |
| Flue gas mass flow [g/s] | 176 |
| Necessary flue draught [Pa] | 11 |

Further important characteristics of the appliance

Suitability for installation to a shared flue 1)



Connectivity to the central heating system

General technical approval for room sealed operation

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

¹⁾ For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

^{*}A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.



This appliance is authorized to use the HKI quality label.

| Evaluation of emission data and efficiency Wood | |
|--|------------|
| Norm : Slow heat release appliances | Evaluation |
| D - 1.BImSchV | Stufe 2 |
| A - Austrian regulation referred to Art 15a B-VG | 2015 |
| CH - Swiss clean air act | ✓ |
| DK - Danish regulation for air pollution from wood burners | ✓ |
| F - Crédit d'impôt à la transition énergétique | ✓ |



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information