

Appliances properties: Accente International GmbH - Casablanca STS - 104749

Master data

Date of entry Aug 23, 2017

Manufacturer Accente International GmbH

Model Casablanca STS

Product code 104749

Nominal heat output [kW] 8

Declared nominal space heating output [kW] 8.48

Continuous burning appliance

Type test standard DIN EN 13240

Year of testing 2015

Test laboratory KONTROL 94 Ltd.

Number of test laboratory 32

Number of test report NB1879-K-06-2015

Flue gas values

	Wood	Coal
Flue gas mass flow [g/s]	8.38	9.74
Flue gas mass flow [g/s]	225	200
Necessary flue draught [Pa]	12	12

Further important characteristics of the appliance

Suitability for installation to a shared flue 1)



Connectivity to the central heating system



¹⁾ For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

^{*}A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.

Evaluation of emission data and efficiency Wood

CH - Swiss clean air act

Norm DIN EN 13240: Roomheater for wood logs	Evaluation
EU - Regulation (EU) 2015/1185 (Ecodesign)	✓
D - 1.BlmSchV	Stufe 2
A - Austrian regulation referred to Art 15a B-VG	✓
CH - Swiss clean air act	✓
DK - Danish regulation for air pollution from wood burners	✓
F - Crédit d'impôt à la transition énergétique	7☆
I - Italian Decree No. 186	*

U-Roomheater accroding to EN 13240	Evaluation
U - Regulation (EU) 2015/1185 (Ecodesign)	✓
- 1.BImSchV	Stufe 2



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information