

Appliances properties: TOPO Accente GmbH & Co. KG - Modena + Granit - 103603

Master data

Date of entry Dec 14, 2015

Manufacturer TOPO Accente GmbH & Co. KG

Model Modena + Granit

Product code 103603

Nominal heat output [kW] 7

Declared nominal space heating output [kW] 7.2

Continuous burning appliance

Type test standard DIN EN 13240

Year of testing 2012

Test laboratory KONTROL 94 Ltd.

Number of test laboratory 32

Number of test report NB1879-K-33-2012 - C

Flue gas values

	Wood	Coal
Flue gas mass flow [g/s]	6.36	7.93
Flue gas mass flow [g/s]	234	227
Necessary flue draught [Pa]	12	12

Further important characteristics of the appliance

Suitability for installation to a shared flue 1)



Connectivity to the central heating system



¹⁾ For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

^{*}A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.

Evaluation of emission data and efficiency Wood

CH - Swiss clean air act

Norm DIN EN 13240 (Intermittent burning): Roomheater with flat-layer firing	Evaluation
D - 1.BImSchV	Stufe 2
A - Austrian regulation referred to Art 15a B-VG	✓
CH - Swiss clean air act	✓
OK - Danish regulation for air pollution from wood burners	✓
- Crédit d'impôt à la transition énergétique	7.

Norm DIN EN 13240 (Intermittent burning): Roomheater with flat-layer firing D - 1.BImSchV A - Austrian regulation referred to Art 15a B-VG



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information