

## Appliances properties: Olsberg GmbH - Olsberg - LEVANA AQUA 2.0 - 43/249

Master data

Date of entry Jan 14, 2022

Manufacturer Olsberg GmbH - Olsberg

Model LEVANA AQUA 2.0

Product code 43/249

Nominal heat output [kW] 8

Declared nominal space heating output [kW] 8

Continuous burning appliance

Type test standard DIN EN 14785

Year of testing 2020

**Test laboratory** Technische Universtität Wien

Number of test laboratory

Number of test report PL-20050-2-P

Flue gas values

	Pellets
Flue gas mass flow [g/s]	7.1
Flue gas mass flow [g/s]	122
Necessary flue draught [Pa]	11.2

Further important characteristics of the appliance

Suitability for installation to a shared flue 1)



Dallata

Connectivity to the central heating system



## General technical approval for room sealed operation

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements\* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

<sup>1)</sup> For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

<sup>\*</sup>A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.

## Evaluation of emission data and efficiency Pellets

EU- Roomheater fired by wood pellets accoding to EN 14785	Evaluation
EU - Regulation (EU) 2015/1185 (Ecodesign)	✓
D - 1.BlmSchV	Stufe 2
A - Austrian regulation referred to Art 15a B-VG	✓
CH - Swiss clean air act	✓
DK - Danish regulation for air pollution from wood burners	✓
F - Crédit d'impôt à la transition énergétique	<b>√</b> 7 <b>☆</b>
I - Italian Decree No. 186	<b>東京政治</b>



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information