

Appliances properties: Olsberg GmbH - Olsberg - Tenorio Compact - 23/684

Master data

Date of entry Nov 27, 2014

Manufacturer Olsberg GmbH - Olsberg

Model Tenorio Compact

Product code 23/684

Nominal heat output [kW] 5

Declared nominal space heating output [kW] 5

Continuous burning appliance

Type test standard DIN EN 13240

Year of testing 2014

Test laboratory RRF Rhein-Ruhr-Feuerstättenprüfstelle GmbH

Number of test laboratory 2

Number of test report RRF - 40 14 3663

Flue gas values

	Wood	Coal
Flue gas mass flow [g/s]	4.7	9.2
Flue gas mass flow [g/s]	250	309
Necessary flue draught [Pa]	12	12

Further important characteristics of the appliance

Suitability for installation to a shared flue 1)

Connectivity to the central heating system

General technical approval for room sealed operation

Number of approval for room sealed operation

Z-43.12-398

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

¹⁾ For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

^{*}A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.

Evaluation of emission data and efficiency Wood

CH - Swiss clean air act

Norm DIN EN 13240 (Intermittent burning): Roomheater with flat-layer firing	Evaluation
O - 1.BImSchV	Stufe 2
- Austrian regulation referred to Art 15a B-VG	2015
H - Swiss clean air act	✓
K - Danish regulation for air pollution from wood burners	✓
- Crédit d'impôt à la transition énergétique	7.4

Evaluation
♦
Grandfathering
_



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information